


April 21, 1987

TO: File

FROM: Frank J. Filas, Reclamation Engineer 

RE: Site Inspection, M/019/009, Cactus Rat - Atlas Minerals

On April 13, 1987, Frank Filas inspected the Cactus Rat Mine area. Conditions were identical to that described and photographed on January 21, 1983. The area consists of numerous open adits and waste piles scattered across the landscape.

The Division had requested Atlas to secure the open holes and portals in January of 1983. This apparently was never done.

Atlas proposed to strip mine this old mining area in 1978, but there is no evidence of this having occurred. There are no assessment notices onsite and the last drilling that Atlas did in the area was in the summer of 1984. Atlas will be contacted in the near future to determine what their future plans are for the property, and for what reclamation they are responsible.

clj
cc: L. Braxton
1115R/85



M/019/009 4-13-87
West End of property

Cactus Rat M/019/009 4-13-87

Living Quarters located on
bend in road

M/019/009 4-13-87
West End of property

4-13-87

Cactus RAT
EAST PORTION OF PROPERTY

Cactus RAT - EAST PORTION
OF PROPERTY

Cactus RAT M/019/009 4-13-87

West End of property

4-13-87 Cactus RAT
EAST PORTION OF PROPERTY

M/019/009 Cactus RAT 4-13-87
OLD TRESTLE - EAST PORTION
OF PROPERTY



M/019/009 Cactus RAT

On East portion of property
looking north

M/019/009 Cactus RAT 4-12-87

EAST End of property

4-14-87

M/019/009

East End of Cactus RAT
Property